New Hampshire Association of REALTORS® Standard Form



TO BE COMPLETED BY SELLER

Comments:

The following answers and explanations are true and complete to the best of SELLER'S knowledge. This statement has been prepared to assist prospective BUYERS in evaluating SELLER'S property. This disclosure is not a warranty of any kind by the SELLER, or any real estate FIRM representing the SELLER, and is not a substitute for any inspection by the BUYER. SELLERS authorize FIRM in this transaction to disclose the information in this statement to other real estate agents and to prospective buyers of this property.

NOTICE TO SELLER(S): COMPLETE ALL INFORMATION AND STATE NOT APPLICABLE OR UNKNOWN AS APPROPRIATE. IF ANY OF THE INFORMATION IN THIS PROPERTY DISCLOSURE FORM CHANGES FROM THE DATE OF COMPLETION, YOU ARE TO NOTIFY THE LISTING FIRM PROMPTLY IN WRITING. SELLER: Robert A. Rolla and Janice D. Denson PROPERTY LOCATION: 32 Sterling Place, Bow, NH 03304 CONDOMINIUM, CO-OP, PUD DISCLOSURE RIDER OR MULTIFAMILY DISCLOSURE RIDER ATTACHED? ✓ Yes SELLER: ☐ has WATER SUPPLY Please answer all questions regardless of type of water supply. TYPE OF SYSTEM: ☐ Public ☐ Unknown Other ☑ Drilled ☐ Dug b. INSTALLATION: Location: Well #1 South of library; Well #2 in south field, 4000 gal fiberglass cistern west of Well #1 Installed By: Capital Well and Gilford Well Date of Installation: new well pump and treatment 2018 What is the source of your information? Capital Well and public documents. **c.** USE: Number of persons currently using the system: 2 Does system supply water for more than one household? ✓ No ☐ Yes MALFUNCTIONS: Are you aware of or have you experienced any malfunctions with the (public/private/other) water systems? □ N/A Pump: ☐ Yes **☑** No Quantity: □ Yes ✓ No **☑** No ☐ Unknown Quality: ☐ Yes If YES to any question, please explain in Comments below or with attachment. WATER TEST: Have you had the water tested? ✓ Yes

☐ No Date of most recent test 2018 IF YES to any question, please explain in Comments below or with attachment. Are you aware of any test results reported as unsatisfactory or satisfactory with notations? 🔽 Yes 📉 No IF YES, are test results available? ✓ Yes ☐ No What steps were taken to remedy the problem? Replaced and expanded water treatment system. August 2018 water test indicated satisfactory results. COMMENTS: New system includes new Radon Water treatment, ultraviolet sanitizer, maganese and iron filter and water softener (EVOLVE Brand); plus new Grundfos well pump and wiring installed 2017 by Capital Well **SEWAGE DISPOSAL SYSTEM** a. TYPE OF SYSTEM: Public: ☐ Yes ☑ No Community/Shared: ☐ Yes ☐ No Private:

✓ Yes

✓ No ☐ Unknown Septic Design Available:

✓ Yes

✓ No b. IF PUBLIC OR COMMUNITY/SHARED Have you experienced any problems such as line or other malfunctions? ☐ Yes ☐ No What steps were taken to remedy the problem? N/A c. IF PRIVATE: TANK: ☐ Cesspool ☐ Unknown ☐ Other ☐ Other Tank Size 250/1250 Gal. ☐ Unknown ☐ Unknown ☐ Other Location: Front of house (hand hole access) ☐ Location Unknown Date of Installation:15+ years Name of Company Servicing Tank: Best Septic Date of Last Servicing: 2018 Have you experienced any malfunctions? ☐ Yes ☑ No Comments: 250 gallon pump chamber and 1250 septic tank. Proactively pumped tank and replaced septic pump in July 2018. d. LEACH FIELD: ✓ Yes ☐ No ☐ Other IF YES, Location: Front of yard __ Unknown Size_{see system design blue print} Instaneu by. Date of installation of leach field: 15+ years
Have you experienced any malfunctions? ☐ Yes ☑ No

New Hampshire Association of REALTORS® Standard Form



TO BE COMPLETED BY SELLER

PROPERTY LOCATION: 32 Sterling Place, Bow, NH 03304												
	e. IS SYSTEM LOCATED ON "DEVELOPED WATERFRONT" as described in RSA 485-A? ☐ Yes ☐ No ☐ Unknown IF YES, has a site assessment been done? ☐ Yes ☐ No ☐ Unknown Source of Information: Comments:Likely not, but RSA485-A is a complex legal document hence unknown. FOR ADDITIONAL INFORMATION THE BUYER IS ENCOURAGED TO CONTACT THE NH DEPARTMENT OF											
	ENVIRONMENTAL SERVICES SUBSURFACE SYSTEMS BUREAU											
7.	INS	<u>ULATION</u>	LOCATION Attic or Cap Crawl Space Exterior Walls Floors Exterior Sheathing	Yes V V V V V V V V V V V V V V V V V V	№ □ □ □ □	Unknown □ □ □ □ □ □ □ □	*Sprayfoam and *fiberglass *Sprayfoam and *Sprayfoam and *Sprayfoam 1 "Styrofoam	6" depth wall cav	vity	Unknown □ □ □ □ □ □ □ □ □ □ □		
8.												
	a. UNDERGROUND STORAGE TANKS - Current or previously existing: Are you aware of any past or present underground storage tanks on your property? Yes No Unknown IF YES: Are tanks currently in use? IF NO: How long have tank(s) been out of service? What materials are, or were, stored in the tank(s)? Age of tank(s): July 2018 installation Size of tank(s): 500 gallon											
			ent to garage under lawn			() ==== 0===						
		Are you aware	of any past or present	t problem	ns such	as leakage, et	c? ☐ Yes ☑ N	lo Comments:				
	b.	If tanks are no longer in use, have the tanks been removed?										
	c	RADON/AIR - C	se was built in 1988 - 199	00 and it is	a: unlikely	to have asbesto	s materials. None u	ised during remod	el.			
	C.	c. RADON/AIR - Current or previously existing: Has the property been tested?										
	d.					Testing	is scheduled for Au	gust 2018				
	d. RADON/WATER - Current or previously existing: Has the property been tested? ✓ Yes ☐ No ☐ Unknown If YES: Date: 2018 By: NH State Laboratory											
	Results: Tested below limits If applicable, what remedial steps were taken? Radon water treatment installed 201° Has the property been tested since remedial steps? ✓ Yes ☐ No Are test results available? ✓ Yes ☐ No Comments: 2018 e. LEAD-BASED PAINT - Current or previously existing: Are you aware of lead-based paint on this property? ☐ Yes ☑ No If YES: Source of information:								it installed 2017			
Are you aware of any cracking, peeling, or flaking lead-based paint?												
			d paint was outlawed in					=	/2018			
SELLER(S) INITIALS SELLER(S) INITIALS SELLER(S										/		

New Hampshire Association of REALTORS® Standard Form



TO BE COMPLETED BY SELLER

PR	OPE	RTY LOCATION: 32 Sterling Place, Bow, NH 03304											
		Are you aware of any other hazardous materials? ☐ Yes ☑ No											
		If YES: Source of information:											
		Comments:											
9.	<u>GE</u>	ENERAL INFORMATION											
	a.	Is this property subject to liens, encroachments, easements, rights-of-way, leases, restrictive covenants, attachments, life											
		estates, or right of first refusal?											
	✓ Yes ☐ No ☐ Unknown If YES, Explain: Declaration of Restrictions for Subdivision of Land												
		What is your source of information? Documents recorded at the Registry											
	b.	Is this property subject to special assessments, betterment fees, association fees, or any other transferable fees?											
		☐ Yes ☑ No ☐ Unknown If YES, Explain:											
		What is your source of information?											
	c. Are you aware of any onsite landfills or any other factors, such as soil, flooding, drainage, etc?												
		☐ Yes ☑ No If YES, Explain:											
	d.	Are you aware of any problems with other buildings on the property? Yes No If YES, Explair _{no other buildings}											
	e.	Are you receiving a tax exemption or reduction for this property for any reason including but not limited to current use, land											
conservation, etc.? ☐ YES ☑ NO☐ UNKNOWN If YES, Explain:													
	f.	Is any part of this property in Current Use? ☐ Yes ☐ No ☐ Unknown If YES, Explain:											
	g.	Is this property located in a Federally Designated Flood Zone? ☐ Yes ☐ No ☐ Unknown											
	h.	Has the property been surveyed? ✓ Yes ☐ No ☐ Unknown If YES, By: WG Howard Surveyors see attached drawing											
		If YES, is survey available? ☐ Yes ☐ No ☐ Unknown											
	i.	How is the property zoned? Residential											
	j.	Heating System Age: see below Type: Forced hot air Fuel: Oil/electric Tank/Location: basement											
		Owner of Tank: Oil Homeowner / Furnace #1 2017, #2 2009, #3 2018, #4 2018. Propane Rymes											
		Annual Fuel Consumption: \$3,500 Price: 2.80 Gallons: 1200											
		Date system was last serviced and by whom? 2018 Johny Prescott Oil Co											
		Solar Panels: Leased Owned If leased, explain terms of agreement:											
		Comments:											
	k.	Roof Age: <u>'04, '17, '18</u> Type of Roof Covering: <u>Premium shingles and metal roofing on shed dormers</u>											
		Moisture or leakage: None											
	_	Comments: Renovated areas received new roof in 2017; new shed dormer over barn/garage 2018											
	I.	Foundation/Basement:											
		Moisture or leakage: Controlled by de humidifier											
		Comments: Some settling cracks, some moisture present in basement following weeks of heavy rains. Repaired August 2018											
		Chimney(s) How Many? 4 Lined? Yes Last Cleaned: Unknown Problems? tuckpoint seal 2015											
	n.	Plumbing Type: copper, PVC, and Aquapex Age: various											
	_	Comments: All renovated areas including kitchen, guest baths, new master bath - new aquapex and PVC. Existing copper and PVC 15 +yea											
	0.	Domestic Hot Water: Age: Rinai 2018 and oil heater 15+ Type: Rinaii gas& oil fired tank Gallons: Tankless Rinai!, 50 tank											
	p.	Electrical System Amps: 200											
	~	Comments:											
	q.	Modifications: Are you aware of any modifications or repairs made without the necessary permits? Yes No											
	_	If Yes, please explain: Pest Infestation: Are you aware of any past or present pest infestations? ☑ Yes ☐ No Type:											
	r.	· · · · · · · · · · · · · · · · · · ·											
	_	Comments: Some evidence of prior mouse activity. House was treated with bait. No additional evidence of rodents since. Methamphetamine Production: Do you have knowledge of methamphetamine production ever occurring on the property?											
	S.												
		(Per RSA 477:4-g)											
	t.	Other (e.g. Alarm System, Irrigation System, etc.) N/A											
61	= 1 1 5	DISCONITIONS REPORTED TO THE PROPERTY OF THE P											
SE	LLE	R(S) INITIALS OS/26/19 J OS/26/19 BUYER(S) INITIALS J											

New Hampshire Association of REALTORS® Standard Form



TO BE COMPLETED BY SELLER

PROPERTY LOCATION: 32 Sterling Place, Bow, NH 03304

NOTICE TO PURCHASER(S): PRIOR TO SETTLEMENT YOU SHOULD EXERCISE WHATEVER DUE DILIGENCE YOU DEEM NECESSARY WITH RESPECT TO ADJACENT PARCELS IN ACCORDANCE WITH THE TERMS AND CONDITIONS AS MAY

BE CONTAINED IN PURCHASE AND SALES AGREEMENT AND DEPOSIT RECEIPT. YOU SHOULD EXERCISE WHATEVER DUE DILIGENCE YOU DEEM NECESSARY WITH RESPECT TO INFORMATION ON ANY SEXUAL OFFENDERS REGISTERED UNDER NH RSA CHAPTER 651-B. SUCH INFORMATION MAY BE OBTAINED BY CONTACTING THE LOCAL POLICE DEPARTMENT.										
	DITIONAL INFORMATION?									
Hor floo Spa sin	b. ADDITIONAL COMMENTS: Home was completely renovated 2016-2018 including new Wolf gas Stove, dishwasher, granite counter tops, ceramic tile floors, siding, windows and doors, paint, and insulation, Master Suite redesigned to maximize valley and mountain views. Spa style Master Bath created with extensive features - heated floors and shower walls, body sprays, multi headed shower, sinks, island with wine refrigerator, coffee maker, and other features, twenty feet of built in closet with master washer and dryer hook up. Modern style soaking tub with air and heated back. Office adjacent to Master Suite upgraded with windows to maximize valley views and views to Presidential mountains. Property to be delivered with 3 new zone air conditioners, one zone heat pump, backup generator, and a new Rinaii on demand 'unlimited' hot water system in addition to existing oil fired hot water tank. Complete exterior house wrap, 1" Styrofoam insulation and Hardie Plank (maintenance free) Maintenance free exterior trim made with Azek/Klear product									
Nev	Maintenance free exterior trim made with Azek/Klear product All New Hi efficient Marvin Windows and doors w Anderson brand for specialty windows and doors. New Garage Doors and motor operators New Deck and wire railings ***Seller to have kitchen/dining room chimney re-flashed to correct leak as soon as warmer temperatures permit ***Seller will deliver property with (2) built-in wine-coolers (kitchen and master bath)									
	* INSULATION: During renovation all exterior siding, wrap and approximate 50% of plywood was replaced with plywood needed, one inch tongue and groove rigid styrofoam, new house wrap, and Hardie Plank cementatious siding. West and North facing walls and ceiling of master bath were spray foamed and/or New insulation batting installed. Loose foam was sprayed into floor of bedroom above pine Room and ceiling of Oak library as well as floor/ceiling of great room.									
ACKNOWL	EDGEMENTS:									
SELLER ACKNOWLEDGES THAT HE/SHE HAS PROVIDED THE ABOVE INFORMATION AND THAT SUCH INFORMATION IS ACCURATE, TRUE AND COMPLETE TO THE BEST OF HIS/HER KNOWLEDGE. SELLER AUTHORIZES THE LISTING BROKER TO DISCLOSE THE INFORMATION CONTAINED HEREIN TO OTHER BROKERS AND PROSPECTIVE PURCHASERS.										
SELLER(S) MAY BE RESPONSIBLE AND LIABLE FOR ANY FAILURE TO PROVIDE KNOWN INFORMATION TO BUYER(S).										
du.	dotloop verified 05/26/19 7:59 PM EDT SYTK-BEM1-8U6D-WQQN	Robert Rolla	dotloop verified 05/26/19 8:09 PM EDT 7CGS-NMJA-RGYW-TEIF							
SELLER	DATE	SELLER	DATE							
BUYER ACKNOWLEDGES RECEIPT OF THIS PROPERTY DISCLOSURE RIDER AND HEREBY UNDERSTANDS THE PRECEDING INFORMATION WAS PROVIDED BY SELLER AND IS NOT GUARANTEED BY BROKER/AGENT. THIS DISCLOSURE STATEMENT IS NOT A REPRESENTATION, WARRANTY OR GUARANTY AS TO THE CONDITION OF THE PROPERTY BY EITHER SELLER OR BROKER. BUYER IS ENCOURAGED TO UNDERTAKE HIS/HER OWN INSPECTIONS AND INVESTIGATIONS VIA LEGAL COUNSEL, HOME, STRUCTURAL OR OTHER PROFESSIONAL AND QUALIFIED ADVISORS AND TO INDEPENDENTLY VERIFY INFORMATION DIRECTLY WITH THE TOWN OR MUNICIPALITY.										
			-							
L BUYER	DATE	l L BUYER	DATE							